

附件二：该房屋损坏构件照片



IMG_5143



IMG_5144




IMG_5145



IMG_5146



IMG_5147



IMG_5148

附件二：该房屋损坏构件照片



IMG_5149



IMG_5150



IMG_5151



IMG_5152



IMG_5153




IMG_5154

附件二：该房屋损坏构件照片



IMG_5155



IMG_5156



IMG_5157



IMG_5158



IMG_5159



IMG_5160

附件二：该房屋损坏构件照片



IMG_5161



IMG_5162



IMG_5163



IMG_5164



IMG_5165



IMG_5169

附件二：该房屋损坏构件照片



IMG_5170



IMG_5171




IMG_5172



IMG_5173




IMG_5174



IMG_5175

附件二：该房屋损坏构件照片



IMG_5176



IMG_5177



IMG_5178



IMG_5179



IMG_5180



IMG_5181

附件二：该房屋损坏构件照片




IMG_5182



IMG_5183



IMG_5184



IMG_5185



IMG_5186




IMG_5187

附件二：该房屋损坏构件照片



IMG_5188



IMG_5189




IMG_5190



IMG_5191




IMG_5192




IMG_5193

附件二：该房屋损坏构件照片



IMG_5194



IMG_5195



IMG_5199



IMG_5200



IMG_5201



IMG_5202

附件二：该房屋损坏构件照片



IMG_5203



IMG_5204



IMG_5205



IMG_5206



IMG_5207



IMG_5208